



Jula item 022936		
Ver. No.	Factory Model	Customer Model
Ver.1.0	WL1000A	PDB 100 A1

No.	Factory Cord	Name	Material Mark	Qty.
1	WL1000A.01	Socket head cap screws	M6*10	3
2	WL1000A.02	Bearing block		2
3	WL1000A.03	Gasket	φ 6	6
4	WL1000A.04	Spring washer	φ 6	6
5	WL1000A.05	Bearing	6004	2
6	WL1000A.06	Nut		6
7	WL1000A.07	Headless line 1		1
8	WL1000A.08	Headless Line 2		1
9	WL1000A.09	driven wheel		1
10	WL1000A.10	Headstock assembly		1
11	WL1000A.11	Jog box bottom		2
12	WL1000A.12	Micro switch (normally open)		2
13	WL1000A.13	Micro-motion lid		2
14	WL1000A.14	Cross screws	M4*35	4
15	WL1000A.15	Anti-folding		1
16	WL1000A.16	upper cover		1
17	WL1000A.17	Power cord + plug		1
18	WL1000A.18	Cross screws	M4*10	2
19	WL1000A.19	Triangle knob		1
20	WL1000A.20	Nut	M4	2
21	WL1000A.21	Nut	M4	4
22	WL1000A.22	Output shaft		1
23	WL1000A.23	Retaining ring for shaft	φ 20	3
24	WL1000A.24	Plum thimble		1
25	WL1000A.25	Retaining ring for shaft	Φ 12	3
26	WL1000A.26	Eccentric bushing		1
27	WL1000A.27	Neck screw		2
28	WL1000A.28	Knife holder fixing plate assembly		1
29	WL1000A.29	Tool holder welding assembly		1
30	WL1000A.30	Socket head cap screws	M8*12	2
31	WL1000A.31	Tool post		1

No.	Factory Cord	Name	Material Mark	Qty.
32	WL1000A.32	Long eccentric shaft		1
33	WL1000A.33	Eccentric shaft handle		1
34	WL1000A.34	Tailstock thimble		1
35	WL1000A.35	Bearing	608	1
36	WL1000A.36	Tailstock screw		1
37	WL1000A.37	Nut	M18	1
38	WL1000A.38	Self-tapping screws	ST3. 5*12	3
39	WL1000A.39	Cross recessed screw	M5*25	1
40	WL1000A.40	Tailstock handwheel		1
41	WL1000A.41	Self-locking nuts	M5	1
42	WL1000A.42	Tailstock welding assembly		1
43	WL1000A.43	Eccentric bushing		1
44	WL1000A.44	Retaining ring for shaft	Φ12	2
45	WL1000A.45	Eccentric shaft		1
46	WL1000A.46	Eccentric shaft handle		1
47	WL1000A.47	Set screw	M8*10	1
48	WL1000A.48	Belt		1
49	WL1000A.49	Driving wheel		1
50	WL1000A.50	Set screw	M8*10	1
51	WL1000A.51	Self-locking nuts	M8	1
52	WL1000A.52	Hexagonal three combination screws	M6*12*10	4
53	WL1000A.53	Motor rotating plate		1
54	WL1000A.54	Gasket	Φ8*16*1.5	2
55	WL1000A.55	Socket head cap screws	M8*20	2
56	WL1000A.56	Motor assembly		1
57	WL1000A.57	Spring washer	Φ8	1
58	WL1000A.58	Body Welding 1		1
59	WL1000A.59	Body Welding 2		1
60	WL1000A.60	Chuck assembly		2
61	WL1000A.61	Self-locking nuts	M12	2
62	WL1000A.62	Socket head cap screws	M8*25	3
63	WL1000A.63	Gasket	Φ8*16*1.5	3
64	WL1000A.64	Spring washer	Φ8	3
65	WL1000A.65	Two combination self-tapping screws	ST2. 9*12	4
66	WL1000A.66	Switch box cover		1
67	WL1000A.67	switch box		1

No.	Factory Cord	Name	Material Mark	Qty.
68	WL1000A.68	Electromagnetic switch		1
69	WL1000A.69	Cross screws	M5*10	4
70	WL1000A.70	Observation window		1
71	WL1000A.71	Woodworking vehicle floor		1
72	WL1000A.72	Phillips screws	M5*10	2
73	WL1000A.73	Hexagon Screw	φ 8*22*2	2
74	WL1000A.74	Spring washer	Φ8	4
75	WL1000A.75	Gasket	M8*20	4
76	WL1000A.76	Nut	M4	2
77	WL1000A.77	lower cover		1
78	WL1000A.78	Cross slot two combination	M4*10	2
79	WL1000A.79	Triangle knob		1
80	WL1000A.80	Self-locking nuts	M5	2
81	WL1000A.81	Bearing retaining ring	PP	1
82	WL1000A.82	Out of the coil		2
83	WL1000A.83	chuck		1
84	WL1000A.84	Allen wrench	M8	1
85	WL1000A.85	Stamping wrench	26-24-17	2
86	WL1000A.86	turning tool		2
87	WL1000A.87	Socket head cap screws	M6*12	3
88	WL1000A.88	Nuts	M10	6
89	WL1000A.89	Spring pad	Φ 10	6
90	WL1000A.90	Pad	Φ 10*25*1.5	6
91	WL1000A.91	Hexagon screw	M10*40	6